







Flexible Abrasives - Quick-Change

★★★
PREMIUM

PREMIUM SCM Quick-Change discs

for steel, stainless steel, nonferrous metals, plastic and wood

Application


- + For reducing surface roughness, smoothing surfaces as well as cleaning and removing welding seams on a wide range of materials
- + Ideal for hard-to-reach places

Advantage

- + Shortest grinding time thanks to easy handling and mounting
- + Versatile application options eliminate the need for 1-3 work steps
- + Best lifetime and very good stock removal

We recommend

- + "EXTRA COARSE/EXTRA MEDIUM" grain for cleaning, for removing rust and burrs and for minimal stock removal
- + "COARSE" grain for cleaning, for removing rust and coatings and for final finishing
- + "MEDIUM" grain for gentle cleaning, for removing burrs and for final finishing
- + "VERY FINE" grain as the final step

Form	Type number	Dimension	Specification	Max RPM	Rec. RPM	PU	
	QDISC-VL	34422740	25 x R	SCM A COARSE	25000	15000	50 Pcs.
	34422743	25 x R	SCM A MEDIUM	25000	15000	100 Pcs.	
	34422746	25 x R	SCM A VERY-FINE	25000	15000	100 Pcs.	
	34580506	38 x R	SCM A COARSE	24000	14500	100 Pcs.	
	34580509	38 x R	SCM A MEDIUM	24000	14500	100 Pcs.	
	34580581	38 x R	SCM A VERY-FINE	24000	14500	100 Pcs.	
	112543	50 x R	SCM A COARSE	24000	14500	50 Pcs.	
	112546	50 x R	SCM A MEDIUM	24000	14500	50 Pcs.	
	112550	50 x R	SCM A VERY-FINE	24000	14500	50 Pcs.	
	112589	50 x S	SCM A COARSE	24000	14500	50 Pcs.	
	112590	50 x S	SCM A MEDIUM	24000	14500	50 Pcs.	
	112591	50 x S	SCM A VERY-FINE	24000	14500	50 Pcs.	
	34072700	75 x R	SCM A EX. COARSE	20000	13000	25 Pcs.	
	112551	75 x R	SCM A COARSE	20000	13000	25 Pcs.	
	34072701	75 x R	SCM A EX. MEDIUM	20000	13000	25 Pcs.	
	112581	75 x R	SCM A MEDIUM	20000	13000	25 Pcs.	
	112588	75 x R	SCM A VERY-FINE	20000	13000	25 Pcs.	